# SAFETY tips
&
MAINTENANCE

FOLLOW THESE GUIDELINES WHEN
SOLDERING

WORKBENCH
Keep your bench clean and tidy

WORKPLACE
Work in a well-ventilated area & use a fume extractor

CLOTHING
Always wear safety glasses and heat resistant gloves

EQUIPMENT
Keep your equipment away from flammable products

WHEN WORKING

Before using the tool, check the cartridge is correctly inserted | Check that metal parts of the tool/stand are clean to ensure a proper connection between the tool and the stand | Always return the tool to the stand when not in use | Handle the equipment with care | Do not leave the appliance unattended when it is on | Do not handle the tips. This can cause burns. Use the cartridge extractor to change the tip.

AFTER WORKING

It's a good practice to unplug your soldering iron during long periods of inactivity | Maintain tip surface clean and tinned prior to storage to avoid tip oxidation | Alcohol can only be used to clean the metal parts | Periodically check all cables, tubes and cleaning accessories. Replace them when necessary.