

For more details and complete indications, consult the Instruction Manual

Set up



1 Mount display onto Charging-Base



2 Connect cables



3 Place tool in Charging-Holder

Charge level

*color blinks when charging



0 - 20%



20 - 50%



50 - 100%

Get started



4 Turn on display 4"



5 Insert cartridge

6 Set temperature and start working

