

## Packing List

The following items are included:



**DT20**  
Glass Solder-Collector ..... 1 unit

0033494-080424

# JBC

www.jbctools.com

## INSTRUCTION MANUAL



### DT20


Glass Solder-Collector  
for DT530

## DT20 Replacement



Be careful when manipulating the tool. The metal and glass parts may be hot.

Hold down the tool with one hand onto the stand (1) and grasp the suction tube at the point where it meets the suction tube connector and pull upward (2) to undock the solder-collector from the heating element guard.



www.jbctools.com



Detach the suction tube connector from the solder-collector by gently pulling both in opposite directions (3). If the solder-collector is too hot, use the heat-resistant gripper provided with the tool.

Then remove both gaskets by pulling out as well.

Use the cleaning brush provided with the tool to push the filters out of the worn DT20 (4).

Replace the worn DT20 and slide back in the new filters (5). Fit the rearward gasket onto the solder-collector (6). Push both filters as far as possible against the rearward gasket using the cleaning brush (7).

Fit the front gasket onto the DT20 and reassemble the solder-collector onto the desoldering iron.

