

# Packing List



**Paper Filters** ..... 1 box

*Contains 50 filters*



**Manual** ..... 1 unit

Ref. 0034617

0034617-151024

MS40 Paper Filters are used with desoldering modules MV-A, MS-A, MVE-A and MSE-A.

# JBC

www.jbctools.com

## INSTRUCTION MANUAL



### MS40

Paper Filters for MS/MSE  
and MV/MVE



www.jbctools.com



# Replacement

Follow these steps to replace the worn paper filters on your desoldering module:

1. Unscrew the filter cover.
2. Remove the paper filters.
3. Replace the worn filters with the new ones (use two).
4. Put the filters back in place and screw the filter cover back on.

