

# UCR470-5A 100/120/230V CONTROL UNIT R470 FOR ROBOT

SPARE PARTS	
<b>UCR470-5A:</b>	
-CIRCUIT	0021143

UCR470-5A 100/120/230V FUSE T-4A

